
Approved For Release 2001/03/17: CIA-RDP82-00457R003700250012-5 Reluin to CIA Library

25X1A



```
I thru III Points from which the photographs were taken

A - B Completed section of the runway

B - C Section of the runway under construction

Rolled and metalled section of the landing field

Neglected and weedy section of the landing field

Concrete aprons used as aircraft parking sites

Area covered with undergrowth and strewn with wrecked aircraft and motor vehicles

Former factory used as workshop

Garden truck and ANNAHOF Estate

Ruined ANTONIENHOF

Ruined WILHELMINENHOF

Hangar

Ruins

Shed

Guardhouse

Quarters of guard detail

Ruined aircraft revetments

Approach road for construction materials
```

25X1A